

Contents	Page
1 Introduction.....	1
2 Scope and purpose	1
3 Current findings	1
4 Preliminary discussion.....	1
5 Recommendations	3
6 Reference.....	4
Figure	
Figure 1—H-W Cylinders (AA6061) fatigue crack initiated from a corrosion pit	2
Figure 2—AA7060 Cylinder metallographic examination according to the intercrystalline test as per BS EN 1975.	2
Figure 3—H-W AA6061 Cylinder metallographic examination according to the intercrystalline test as per BS EN 1975.	3