

AWS D10.12M/D10.12:2000
An American National Standard



Guide for Welding Mild Steel Pipe



American Welding Society



Key Words—Mild steel pipe, tubing, shielded metal arc welding, oxyacetylene welding, gas tungsten arc welding, gas metal arc welding, flux cored arc welding

AWS D10.12M/D10.12:2000
An American National Standard

Approved by
American National Standards Institute
July 20, 2000

Guide for Welding

Mild Steel Pipe

Supersedes ANSI/AWS D10.12-89

Prepared by
AWS D10 Committee on Piping and Tubing

Under the Direction of
AWS Technical Activities Committee

Approved by
AWS Board of Directors

Abstract

This document presents recommended practices for welding mild steel pipe. It is intended to cover piping systems such as for low pressure heating, air conditioning, refrigeration, water supplies, as well as some gas or chemical systems. It provides welding techniques for oxyacetylene, shielded metal arc, gas tungsten arc, gas metal arc, and flux cored arc welding. This document does not address the needs of pipe steels or service conditions which may require Post Weld Heat Treatment (PWHT).



American Welding Society

550 N.W. LeJeune Road, Miami, Florida 33126

Table of Contents

	Page No.
<i>Personnel</i>	iii
<i>Foreword</i>	v
<i>List of Tables</i>	viii
<i>List of Figures</i>	viii
1. Scope	1
2. Reference Documents	1
2.1 AWS Pipe Standard Welding Procedure Specifications	2
3. General	2
3.1 Pipe Steels	2
3.2 Cleanliness	2
3.3 Preheating	2
3.4 Joint Preparation	2
3.5 Alignment and Tack Welding	2
3.6 Welding Positions	2
3.7 Weld Appearance	2
3.8 Small Diameter Piping	3
3.9 Welding Fittings	4
3.10 Safety and Health	4
4. Shielded Metal Arc Welding (SMAW) Using E6010 Electrode and the Downhill Method	4
4.1 Application	4
4.2 Setting the Current	4
4.3 Tack Welding	4
4.4 Root Pass (First Pass)	7
4.5 Manipulating the Electrode	7
4.6 Cleaning Between Passes	7
4.7 Second Pass (Hot Pass)	7
4.8 Fill, Stripper, and Cap Passes	7
5. Shielded Metal Arc Welding (SMAW) Using E6010 or E6011 Electrodes and the Uphill Method	7
5.1 Application	7
5.2 Joint Preparation	10
5.3 Setting the Current	10
5.4 Root Pass	10
5.5 Cleaning Between Passes	10
5.6 Fill and Cap Passes	10
6. Shielded Metal Arc Welding (SMAW) Using E7018 Low Hydrogen Electrodes	11
6.1 Application	11
6.2 Striking the Arc	11
6.3 Welding Technique	11
6.4 Slag Removal	12
7. Oxyfuel Gas Welding (OFW) of Pipe	12
7.1 Application	12
7.2 Safe Practices	12

7.3	Welding Techniques	12
7.4	Appearance of Finished Weld	15
8.	<i>Gas Tungsten Arc Welding (GTAW) of Pipe</i>	15
8.1	Application.....	15
8.2	Purging	15
8.3	Electrode Shape	15
8.4	Welding Technique	15
8.5	Joint Preparation and Alignment	15
8.6	Appearance of Finished Welds	15
9.	<i>Gas Metal Arc Welding (GMAW) and Gas Shielded Flux Cored Arc Welding (FCAW-G) of Steel Pipe</i>	15
9.1	Application of the GMAW Process	15
9.2	Application of the Gas Shielded Flux Cored Arc Welding (FCAW-G) Process.....	17
9.3	Initiating the Arc	17
9.4	Travel Speed.....	17
9.5	Gas Shielding	18
9.6	Cleaning	18
10.	<i>Flux Cored Arc Welding—Self-Shielded (FCAW-S)</i>	18
10.1	Application.....	18
10.2	Root Pass Techniques Using 1.7 mm (0.068 in.) E71T-13 Electrode.....	18
10.3	Welding Techniques for Balance of Weld.....	20
11.	<i>Nick Break Test</i>	23
12.	<i>Safety and Health</i>	23
12.1	Fumes and Gases	23
12.2	Radiation	23
12.3	Electrical Hazards	24
12.4	Fire Prevention	24
12.5	Burn Protection	25
12.6	Further Information.....	25
	<i>Annex A—Pipe Standard Welding Procedure Specifications</i>	27
	<i>Annex B—Glossary of Terms</i>	29
	<i>Annex C—Required Filler Metal per Joint for Mild Steel Pipe</i>	31
	<i>Annex D—Inspection and Testing</i>	35
	<i>Annex E—Guidelines for Preparation of Technical Inquiries for AWS Technical Committees</i>	37
	<i>AWS List of Documents on Piping and Tubing Welding</i>	39

List of Tables

Table	Page No.
1 Procedures for Circumferential Butt Joints Welded with SMAW Process Using E6010 Electrode with Electrode Pressure for Root Pass	6
2 Procedures for Circumferential Butt Joints Welded with SMAW Process Using E6010 Electrode	10
3 Procedures for Circumferential Butt Joints Welded with SMAW Process Using E6010 and E7018 Electrodes.....	13
4 Procedures for Circumferential Butt Joints Welded with OFW Process	16
5 Procedures for Circumferential Butt Joints Welded with GTAW Process	17
6 Procedures for Circumferential Butt Joints Welded with GMAW Process	18
7 Procedures for Circumferential Butt Joints Welded with GMAW Process for Root Pass and Gas Shielded FCAW Process for Fill and Cap Passes	19
8 Procedures for Circumferential Butt Joints Welded with Self-Shielded FCAW Process	21
9 Procedures for Circumferential Butt Joints Welded with SMAW Process for Root Pass and Self-Shielded FCAW Process for Fill and Cap Passes	22
C1 Filler Metal Required per Joint for Mild Steel Pipe.....	32

List of Figures

Figure	Page No.
1 Terminology for Butt Joint.....	2
2 External Pipe Clamps.....	3
3 Welding Position—Pipe Welds	4
4 Socket Joint	4
5 Typical Welding Fittings and Flanges.....	5
6 Picture of Large Hole at End of Tack Weld	7
7 Keyhole Size Controls Weld Quality	8
8 Typical Pass Sequence and Terminology for Downhill Welding.....	8
9 Effect of Electrode Work Angle on Pass Shape	9
10 Effect of Electrode Travel Angle on Joint Penetration	9
11 Grinding to Improve Root Pass Contour.....	9
12 Electrode Movement for Uphill Welding—Root Pass	11
13 Electrode Movement for Uphill Fill Passes	12
14 Typical Side-to-Side Weave Used for Uphill Last Pass (Cap Pass).....	12
15 One-Pass Forehand Oxyacetylene Welding	14
16 One-Pass Backhand Oxyacetylene Welding	14
17 Position of Gas Nozzle, Contact Tip, and Pipe (GMAW or FCAW-G)	20
18 Position of Gun Nozzle, Contact Tip, and Work Piece (FCAW-S).....	23
C1 Typical Joint	31

Guide for Welding Mild Steel Pipe

1. Scope

This guide is intended to cover such piping systems as low pressure heating, air-conditioning, refrigeration, and water supply, as well as some gas and chemical systems. These procedures include detailed welding process techniques that may be useful for teaching welders. Processes included are Shielded Metal Arc Welding (SMAW), Gas Metal Arc Welding (GMAW), Gas Tungsten Arc Welding (GTAW), Gas Shielded Flux Cored Arc Welding (FCAW-G) Flux Cored Arc Welding—Self-Shielded (FCAW-S), and Oxyfuel Welding (OFW). Qualification of these procedures to any welding standard is the responsibility of the user. This document does not address the needs of pipe steels or service conditions which may require post weld heat treatment (PWHT).

This standard makes use of both the International System of Units (SI) and U.S. Customary Units. The measurements may not be exact equivalents; therefore, each system must be used independently of the other without combining in any way. The standard with the designation D10.12:2000M uses SI Units. The standard designation D10.12M:2000 uses U.S Customary Units. The latter are shown within brackets () or in appropriate columns in tables and figures. Pipe sizes are listed as DN (diameter nominal) and NPS (nominal pipe size). The exact pipe diameters are in Table C1.

2. Reference Documents

AWS D10.11, *Recommended Practices for Root Pass Welding of Pipe Without Backing*

AWS A3.0, *Standard Welding Terms and Definitions*

ANSI Z49.1, *Safety in Welding, Cutting, and Allied Processes* (available from the American Welding Society)

AWS *Safety and Health Facts Sheets*

AWS A5.1, *Specification for Carbon Steel Electrodes for Shielded Metal Arc Welding*

AWS A5.2, *Specification for Carbon and Low-Alloy Steel Rods for Oxyfuel Gas Welding*

AWS A5.12/A5.12M, *Specification for Tungsten and Tungsten Alloy Electrodes for Arc Welding and Cutting*

AWS A5.18, *Specification for Carbon Steel Electrodes and Rods for Gas Shielded Arc Welding*

AWS A5.20, *Specification for Carbon Steel Electrodes for Flux Cored Arc Welding*

AWS A5.32/A5.32M, *Specification for Welding Shielding Gases*

AWS B1.10, *Guide for Nondestructive Examination of Welds*

AWS B1.11, *Guide for the Visual Inspection of Welds*

AWS B2.1, *Standard for Welding Procedure and Performance Qualification*

AWS B4.0, *Standard Methods for Mechanical Testing of Welds*

AWS F4.1, *Recommended Safe Practices for Preparation for Welding and Cutting of Containers and Piping*

ASME Boiler and Pressure Vessel Code; Section IX, *Qualification Standard for Welding and Brazing Procedures, Welders, Brazers, and Welding and Brazing Operators*¹

API 1104, *Standard for Welding Pipelines and Related Facilities*²

1. American Society of Mechanical Engineers, 3 Park Avenue, New York, NY 10016, (212) 591-8500.

2. Available from the American Welding Society and from the American Petroleum Institute, 1220 L Street NW, Washington DC 20005, (202) 682-8000.