First edition 2003-08-15

Methods for the calibration of vibration and shock transducers —

Part 21:

Vibration calibration by comparison to a reference transducer

Méthodes pour l'étalonnage des transducteurs de vibrations et de chocs —

Partie 21: Étalonnage de vibrations par comparaison à un transducteur de référence



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2003

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents		Page	
Fore	word	iv	
Introduction		v	
1	Scope	1	
2	Normative references	1	
3	Uncertainty of measurement	2	
4	Requirements for apparatus and environmental conditions		
4.1 4.2 4.3 4.4 4.5 4.6 4.7 4.8 5 5.1 5.2 5.3	General Environmental conditions Reference transducer Vibration generation equipment Voltage measuring instrumentation Distortion measuring instrumentation Oscilloscope Phase shift measuring instrumentation Calibration Preferred amplitudes and frequencies Measurement requirements Calibration procedure	3467777	
6	Expression of results		
7	Reporting the calibration results		
Anne	ex A (normative) Expression of uncertainty of measurement in calibration	11	
Anne	x B (normative) Definitions of amplitude sign and phase shift between mechanical motion and vibration transducer electrical output	20	
Anne	ex C (informative) Nomogram for conversion between acceleration, velocity and displacement	22	
Anne	ex D (informative) Example of uncertainty calculation	24	
Biblio	ography	29	

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 16063-21 was prepared by Technical Committee ISO/TC 108, *Mechanical vibration and shock*, Subcommittee SC 3, *Use and calibration of vibration and shock measuring instruments*.

This first edition of ISO 16063-21 cancels and replaces ISO 5347-3:1993, which has been technically revised.

ISO 16063 consists of the following parts, under the general title *Methods for the calibration of vibration and shock transducers*:

- Part 1: Basic concepts
- Part 11: Primary vibration calibration by laser interferometry
- Part 12: Primary vibration calibration by the reciprocity method
- Part 13: Primary shock calibration using laser interferometry
- Part 21: Vibration calibration by comparison to a reference transducer
- Part 22: Shock calibration by comparison to an accelerometer, velocity or force transducer

Introduction

The ISO 16063 series of standards is concerned with methods for the calibration of vibration and shock transducers under both standard laboratory conditions and in the field.

As such, the intended user group of this part of ISO 16063 is wide, ranging from metrologists in mechanical vibration to technicians evaluating the vibration characteristics of a machine or structure, or human exposure to vibration. The key to the application of this part of ISO 16063 is in the careful detailed specification and evaluation of measurement uncertainty, i.e. the error budget and computation of expanded uncertainty associated with the measurement of vibration.

This part of ISO 16063 is particularly intended for those engaged in vibration measurements requiring traceability to primary national or international standards through a secondary, reference, working or check standard (portable calibrator intended for field use) as defined in the *International vocabulary of basic and general terms in metrology* (VIM). The specifications for the instrumentation and the procedures given are intended to be used for calibration of rectilinear vibration transducers (with or without signal conditioning) to obtain the magnitude and (optionally) phase shift of the complex sensitivity at frequencies in the range of 0,4 Hz to 10 kHz.