

<b>Contents</b>	<b>Page</b>
1 Introduction.....	1
2 Scope .....	1
3 Definitions.....	2
4 Inspection equipment .....	5
4.1 Depth gauges, scales, etc. ....	5
4.2 Ultrasonic devices .....	5
4.3 Magnetic particle inspection .....	5
4.4 Penetrant inspection materials .....	6
5 Low pressure cylinders exempt from hydrostatic testing.....	6
5.1 Preparation for inspection .....	6
5.2 Exterior inspection .....	6
5.3 Inspection report.....	13
6 Low pressure cylinders subject to hydrostatic testing .....	13
6.1 Preparation for inspection .....	13
6.2 Internal inspection .....	13
7 High pressure cylinders.....	14
7.1 Preparation for inspection .....	14
7.2 Hammer test.....	14
7.3 Exterior inspection.....	14
7.4 Internal inspection .....	22
8 References .....	22

**Tables**

Table 1—Minimum allowable design thickness ( $t_d$ ) for certain common sizes of low pressure cylinders .....	7
Table 2—Factors for calculation of minimum allowable design thickness ( $t_d$ ) for DOT-3A and DOT-3AA high pressure cylinders .....	16

**Figures**

Figure 1—Crevice corrosion near the cylinder footing.....	2
Figure 2—Crevice corrosion (cutaway view).....	2
Figure 3—General corrosion with pitting.....	3
Figure 4—General corrosion with pitting on cylinder wall .....	3
Figure 5—Isolated pitting .....	3
Figure 6—Line corrosion.....	4
Figure 7—Measuring the length of a typical dent.....	5
Figure 8—Relative pitted depth corrosion loss .....	8
Figure 9—Bulged cylinder on left, normal cylinder on right.....	10
Figure 10—Cylinder section on left with removable boot; cylinder section on right with permanent boot (cutaway side view) .....	12
Figure 11—Cylinder section on left with removable boot; cylinder section on right with permanent boot (cutaway bottom view).....	13
Figure 12—Inspection requirements for corrosion limits .....	15
Figure 13a—Evaluation of pit diameters for an isolated pit.....	17
Figure 13b—Evaluation of pit diameters for isolated pits .....	17
Figure 14a—Evaluation of cluster pitting that may be considered an isolated pit .....	18
Figure 14b—Evaluation of cluster pitting that shall be considered an area of general corrosion .....	18
Figure 15—Bulged fire-damaged cylinder.....	20
Figure 16—Example of an attachment (cylinder with removable boot).....	21

**Appendix**

Appendix A—Sample visual inspection report form (Informative).....	24
--	----